



DO select correct
stroke sizes.

DO minimize internal
motor strain.

DO NOT
force fine liners.
DO NOT push
heavy saturation.



Appropriately sized strokes yield better results and reduce machine strain.
MATCH YOUR MACHINE TO THE SPECIFIC TASK.