




1. Post, end, and
threading
2. Scratches, crevices,
poor polishing
3. Damaged protective
oxide layers
4. Exposed solder
or brazing
5. Mixed-metal
components
6. Finished surface
7. Local corrosion

Damaged finishes, mixed components, and exposed solder alter local corrosion and ion release.

SURFACE CONDITION IS CENTRAL