



Fresh plastic surface barriers must cover all high-touch equipment before the practitioner begins the procedure.

Complete mummification is an extreme but undeniably effective approach to cross-contamination.