Polymer retainers remain completely invisible.

Titanium 136

material is safe.

316L steel contains hidden martensite.

Unknown base plating poses risks.

Cold working makes austenitic stainless alloys dangerously ferromagnetic over time.

NEVER SCAN PLATED METALS.