DO NOT use threaded polymers.

Separate threaded ends rotate freely.

DO use monolithic molded components.

Fixed orientation prevents decorative migration.

Extruded threads rotate freely while injection molding locks orientation.

ELIMINATE THREADED ROTATION FAILURES.