

DO



DO match all metal components.

DO NOT



DO NOT mix metal types.
Mixed metals cause galvanic corrosion.
Corrosion delays the healing process.

A titanium post with a steel closure creates a bimetallic couple.
PREVENT WOUND CONTAMINATION