Disinfect area with 70 percent alcohol.

Remove bead from threaded bar.

Place plastic catheter over tip.

Push jewelry out of skin.

Reverse steps exactly to reinsert barbell after examination.
LEAVE CATHETER AS SPACER.