

Unscrew the bottom battery cap.

Insert the charged lithium cell.

 **Ensure correct battery polarity.**

Secure the cap in 2 clicks.

Proper exchange maintains continuous power without disrupting the workflow.

Slide the control unit closed.