



Over-lubricating a tattoo machine internally voids the manufacturer warranty.

A flooded motor is a highly expensive way to prevent friction