

Protect your equipment



Use cold sterilization methods
Use germicidal agents safely



Do not autoclave motors

High heat destroys internal brushless motors and lithium power units.
HEAT DESTROYS MACHINES