




Fresh piercings require lower migration limits due to open wound sensitivity.

VERIFY ALLOY MIGRATION RATES