Request residual solvent analysis data.

Verify epoxy packaging components.

Update supplier material declarations.

Acceptable solvent parts-per-million limit: 50

Solvents are processing residuals rather than active ingredients.