

Heavy metal limits in body jewellery are applied per individual part rather than averaged across the complete item. A bad jump ring ruins the entire caper