



Non-membrane cartridge needles allow liquid to be sucked back into the machine.
The tool has developed a drinking problem.