



Over-lubricating a machine attracts dust and ink particles.

Friction is actually a required feature.