

**Constant high voltage
causes skin trauma.**

**High voltage wears
out the motor.**

**Keep voltage settings
below 10 volts.**

**Lower speeds produce
better healed results.**



Pushing high voltage causes severe wear on moving parts.

KEEP VOLTAGE BELOW TEN