


Expect 5 to 10 hours runtime.
Look for 8 hours minimum capacity.



Keep spare batteries fully charged.
Swap batteries during long tattoo sessions.

Lithium battery packs eliminate cord clutter but require management.

ALWAYS PREPARE SPARE BATTERIES