



Implant grade stainless steel requires vacuum arc remelting to reduce impurities and prevent the release of trapped elements.
Household cleaning appliances cannot synthesize surgical alloys.