

**Dissimilar metals
accelerate local
corrosion.**

**Body fluids act
as electrolytes.**

**Ions leach directly
into wounds.**

**Maintain uniform
material choices.**



Mixing metal types creates dangerous bimetallic galvanic corrosion couples.

NEVER MIX HEALING METALS.