



Sterilization pouches that remain wet after an autoclave cycle are considered compromised and unsafe.

The rain washes away the indoor moisture