Using tap water in a steam sterilizer causes chloride-induced pitting corrosion that ruins the pressure chamber.

**The machine requires purer hydration than the operator.**