




Metal requires internal thread machining.
The central shaft remains hollow.
Tissue fluid migrates inward slowly.

Biological debris becomes
permanently trapped.

The hollow channel required for internal threading creates a sealed biological cavity.
Hollow shafts trap stagnant body fluids.