



Craft store graphite tracing paper melts inside thermal stencil printers and destroys the hardware.

A trip to the arts and crafts aisle is an expensive way to buy a broken printer.