



Wrinkling typically occurs due to poor paper alignment or trapped moisture in the thermal paper.

Cultivating a tropical microclimate near the equipment rarely improves feeding mechanisms.