


Gauge requires exact diameter matching
Threading type must perfectly align



You need three measurements to buy fitted jewellery safely.
Guessing wrong causes severe injury.