

1

1. Preliminary immersion.

2

2. Mechanical cleaning.

3

3. Chemical disinfection.

4

4. Steam sterilization.

**Tools breaching skin require a strict sequence to guarantee absolute sterility.
EXECUTE THE FOUR STEPS IN ORDER**