

For flexible polymer retainers, the controlling mechanism of failure is almost always the depletion of protective antioxidants.

Sweeping up shadows is rarely effective.