



If the unprocessed control vial fails to show growth, the indicators are compromised and the test is invalid.

THE SPORES ARE STAGING A SILENT STRIKE.