




Instruments packed tightly together prevent steam penetration and will cause the sterilization cycle to fail.
Cramming every single tool into the chamber at once is a triumph of spatial geometry and a catastrophic failure of hygiene.