





Using improper water like old distilled or tap water in the autoclave is a common cause of equipment failure.

Watering the autoclave with premium sparkling mineral water does not make the sterilization cycle any fancier.