




Visible damage or flattening of the silicone door gasket prevents the autoclave from holding pressure.

Fixing a broken high-pressure steam seal with decorative tape is optimism taken to its illogical extreme.