

Ultimate
validation
technique!



Consecutive
testing
combo!



Lethality achieved!



After correcting the root cause, multiple consecutive passing spore tests are required before the autoclave returns to service.

Defeating the broken machine requires unleashing the ultimate consecutive testing combo attack.