




Polymethyl methacrylate absorbs moisture and cracks under extreme sterilization temperatures.
Always use hydrolysis-stable materials for safe clinical practice.