




Every procedure surface must be non-porous and seamless to eliminate micro-reservoirs.

SEAMLESS SURFACE MATERIALS