


*Stainless steel
work surfaces.*



*Washable painted
drywall ceilings.*



Sealed epoxy resin floors.

Every surface must be non porous chemical resistant and seamless.
ELIMINATE MICRO RESERVOIRS IN THE STUDIO.