

**COMMODITY STEEL RISKS
PERMANENT DAMAGE.**



**STOP GUESSING
CLIENT ALLERGY STATUS.**

**SWEATING ACCELERATES
METAL CORROSION QUICKLY.**



**USE ONLY
ZERO NICKEL MATERIALS.**

**SUBSTITUTE STEEL WITH VERIFIED ASTM F136 OR ASTM B392 ALLOYS.
NEVER USE STEEL FOR INITIAL PIERCINGS**