




Heavy metals and nickel release must stay below regulatory thresholds.
USE COMPLIANT METALS