




Combining dissimilar metals in jewellery accelerates galvanic corrosion and releases excess ions into healing tissue.
Building miniature batteries is an awful way to accessorise.