




Blood plasma contact accelerates metal leaching during the open-wound healing phase.
FRESH WOUNDS REQUIRE STRICT $0.2 \mu\text{g}/\text{cm}^2/\text{wk}$ LIMITS.