

Biological Spore Test Failure Protocol

Quarantine immediately.

Quarantine the sterilizer immediately.



Stop all use of the machine.



Recall all recently processed instruments.

**A positive biological test indicates a severe sterility breach.
DO NOT IGNORE FAILURES.**