




MAINTAIN A STEADY POWER SUPPLY.

KEEP VOLTAGE ABOVE 7 VOLTS.

KEEP VOLTAGE BELOW 9 VOLTS.

SET STROKE TO 3 MILLIMETERS.

MAXIMUM STROKE IS 5 MILLIMETERS.

AVOID ERRATIC MACHINE BOUNCING.

CONSISTENT VOLTAGE PREVENTS UNEVEN SATURATION AND MINIMIZES DERMAL TISSUE TRAUMA.

CONTROL YOUR MACHINE SPEED.