

- 
- 1 Request mill test certificate**
 - 2 Confirm exact material standard**
 - 3 Locate unique heat number**
 - 4 Match with current inventory**

The certificate must trace back to the original metal batch.

Always match documentation to the supplied product.