




Combining dissimilar metals in a piercing causes galvanic corrosion when in contact with perspiration.

You are not a battery.