



Metals used for initial piercings must have a consistent mirror finish free of nicks and scratches. Polishing an object out of existence is an extreme but effective way to eliminate surface defects.