



Running an ultrasonic tank without degassing reduces cleaning effectiveness by an estimated 30 to 50%.

Manual bubble extraction remains an inefficient use of studio hours.