DO hold instruments by the main shaft.

DO NOT touch tips with nitrile gloves.

Glove texture destroys precision cutting geometry.

Diioelivved destroys precision cutting geometry.

A single incidental contact compromises the sharpest tip.

PROTECT THE APEX AT ALL TIMES.