



Wash hands with soap.

Apply fresh nitrile gloves.

Apply surface barrier films.

Dispose sharps in container.

Treat all human blood and fluids as highly infectious.
Execute this protocol every time.